	er ID 63887 nber 18, 2010 10:11:01	AM									Page 1
Revision ID:	D4271-011 PRELIM Fwd Beam Assembly	,	4	Accept				s s	etup Sta	1 (221)	
Start Date: Required Date: Reference:	11/18/2010 Start Qty 11/22/2010 Req'd Qt	•			Cust Item 1 Customer:	PR		MNAF		SUE	8 } 8
Approvals:	Process Plan:QC:	<u></u>	Date: 10-11-18	Tooling: SPC (Y/N):		ate:		K	tun Star Sto	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Sequence ID/ Work Center ID	Operation Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D4271 100 Small Fab Small Fab		Memo 1- Pick and	Assemble as per dwg	0.00	B	16.11.	19	0_	÷		P70
QC Quality Control		et part compl	eteness to step on W/O	0.00 S (0 0.00 - (A) PREL	14/22 100 + Pa) m only @						
120 Packaging		er dwg & St	ock Location:	0.00	test.						
Packaging											

Work Order ID 63887

Thursday, November 18, 2010 10:11:01 AM



Page 2

Item ID:

D4271-011

PRELIM

Revision ID: Item Name:

Fwd Beam Assembly

Start Date:

11/18/2010

Start Qty: 2.00

Required Date: 11/22/2010

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

QC:

Operation

Description

QC21- Final Inspection - Work Order Release

Date: Date:

Tooling:

SPC (Y/N):

Accept

Set Up/

Run Hours

Tool ID

Date:

Date:

Tool # Plan

Code

Accept Qty

Reject Qty

Run

Reject Number

Insp. Stamp

130

Quality Control

Sequence ID/

Work Center ID

Memo

0.00

0.00

Setup Start

Stop

Start

Stop

10.11.23 pay PTO D4274-1

POSITIVE RECALL

EFFECTIVE

NUF 10-11-30

__ AUTH ____ RELEASED DATE

Thursday, November 18, 2010 10:11:01 AM

Work Order ID: 63887

Parent Item:

D4271-011

Parent Item Name: Fwd Beam Assembly



Start Date: 11/18/2010

Required Date: 11/22/2010

Start Qty: 2.00

Required Qty: 2.00


Com	ments:	
VUIII	ments.	

IPP rev:A 10.11.18 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4149-5 Eyebolt Stud	BIN 60	Manufactured	No			100	Each	9.0000		B60	790	101	1.195
				Location	1	Loc	<u>Oty</u>	Loc Code	•				1
				GA			9				_		
	•				61234		9						
N D4274-1	6399	Manufactured	No			100	Each	0.0000	2	4	10.11-	19	2
✓ D4275-1		Manufactured	No			100	Each	0.0000		2 16	10 - 11	.19	0
D4281-1 Spacer D6 25		Manufactured	No			100	Each	0.0000	1	2 A	10-11	.19 (<i></i>
AN3C12A		Purchased	No			100	Each	61.0000	8	16	> 10.	11.19	@ 8
				Location	1	Loc	<u>Qty</u>	Loc Code					
				ST351			61		-		_		
					112314		8				_		
					114761		11 42		- magain	199	_		

Thursday, November 18, 2010 10:11:01 AM

Work Order ID: 63887 D4271-011 Parent Item: Parent Item Name: Fwd Beam Assembly Required Date: 11/22/2010 Start Date: 11/18/2010 Required Qty: 2.00 Start Qty: 2.00 MS20615-4M18 No 100 391.0000 Purchased Each Rivet Location Loc Qty Loc Code ST323 391 152 114808 239 100 MS21043-3 Each 2,226.000 Purchased No Nut Location Loc Oty Loc Code FG 76 t 103691 76 ST301 2150 2150 NAS1149C0332R No 100 Each 4,239.000 16 32 Purchased Washer Loc Qty Loc Code Location ST297 4239 113524 10 113737 150 115000 125 115698 35 1919 2000



COPYRIGHT © 2016 BY DART AEROSPACE LTD

IN PRIVATE AND CONTIDENTIAL AND IS SUPPLIED ON THE EXPRESS SOUND!

DEPRIVATION PLANTING OF COPIED OR COMMANDATED TO ANY OTHER RESS.

